Weathertzanton Assistance Program

Work Order (Bid Form)

WORK ORDER INFORMATION

Work Order Name: 14014SO1493
Work Order Type: Weatherization
Audit Name: 14014SO1493

CLIENT INFORMATION

Client Name: 14014SO1493 Address: , Unit 1301

Client ID: 14014SO1493 Culleoka, TN 38451

Alt. Client ID: Maury

CLIENT CONTACT INFORMATION

14014SO1493 Applicant/Person of Record

AGENCY INFORMATION

Agency: South Central Human Resource Agency Agency Phone: (931) 433-7182

Address: 1437 Winchester Highway Fax: (931) 438-0074

Fayetteville, TN 37334 *Email Address:*

Agency Contact: Ford, Duane Work Phone:

Cell Phone: (615) 308-7878

Email Address: Fordd@hughes.net

Company Name & License Number:	
Contractor's Signature:	

COMMENT

I.5 story home in fair cond. Very leaky and cluttered.

Client Name: 14014SO1493 Client ID: 14014SO1493 Alt. Client ID: Maury Work Order (Bid Form)
Work Order Name: 14014SO1493
Report Run On: 5/14/2010

DOE Weatherization Assistant Version 8.5.0

Page 1 of 6

Measures

Measu	re 1	Infiltr	ation Redctn				Compone	nts			Inspected
Comme	Comment 1. Extensive air seal. 2. Replace 3 broken windows. 3. Mastic return air plenum. 4. Repair water leak, roof. 5. Clear caulk fireplaces, crown, jambs, casing, and window seats. 6. Foam plumbing intrusions. 7. Repair wall over kitchen door. 8. Install crown in laundry and caulk to air seal. 9. Repair wall in laundry room. 10. Caulk and air seal upstairs bedroom's walls, doors, and closets. 11. Repair ductwork and mastic registers. 12. Install elect. Cover on panel.										
			, , , , , , , , , , , , , , , , , , , ,				Estimate	ed		Actual	
# Materia	al / Lab	or	Description / Comment	t Ur	nits	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1 Miscel Supplie		S	Infiltration Reduction	Ead	ch	1					
2 Labor			Labor	Но	ur	10					
Other De	tail					Measure	e Sub Total:			Sub Total:	
Field N	otes:										

Measure 2 li Comment	nstall/Replace Heatpump a	nd AC	Components Heat Pump,PKG					Inspected
				Estimated	1		Actual	
Material / Labor	r Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
Heating Equipment	Replace HVAC System	Each	1					
Labor	Labor	Each	1					
Other Detail								
			Measur	e Sub Total:] ;	Sub Total:	
	Replace Back Door Unit, W	S, DS, Lo	ck	Componen				Inspecte
Comment				Estimated	1		Actual	
Comment Material / Labor		S, DS, Lo <i>Units</i> Each	Ck Qty 1	•		Qty		Inspecte Total
Comment Material / Labor Doors	r Description / Comment Back Door Unit, WS,	Units	Qty	Estimated	1	Qty	Actual	
Comment Material / Labor Doors Labor	Pescription / Comment Back Door Unit, WS, DS, Lock	<i>Units</i> Each	Qty 1	Estimated	1	Qty	Actual	
Comment Material / Labor Doors Labor	Pescription / Comment Back Door Unit, WS, DS, Lock	<i>Units</i> Each	Qty 1	Estimated	1	Qty	Actual	
Comment Material / Labor Doors Labor	Pescription / Comment Back Door Unit, WS, DS, Lock	<i>Units</i> Each	Qty 1	Estimated	1	Qty	Actual	
Measure 3 F Comment # Material / Labor 1 Doors 2 Labor Other Detail	Pescription / Comment Back Door Unit, WS, DS, Lock	Units Each Hour	Qty 1	Estimated	1		Actual	

Measure 4 Inst	all Digital Thermostat			Componen	ts HVAC			Inspected
				Estimated	1		Actual	
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1 Unspecified	Digital Thermostat	Each	1					
2 Labor	Labor	Hour	1					
Other Detail			1					
			Measur	e Sub Total:			Sub Total:	
Field Notes:								
Measure 5 DW	H Pipe Insulation			Componen	ts DWH			Inspected
				Estimated	<u> </u>		Actual	
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1 Insulation	DHW Pipe Insulation	Each	1					
	All corners must be cut properly. Refer to Appendix A- Standards for Weatherization Materials and Southeast Field Guide.							
2 Labor	DHW Pipe Insulation	Each	1					
Other Detail								
			Measur	e Sub Total:			Sub Total:	
Field Notes:								

nated ost Total ostal:	Sub Total:
otal:	Sub Total:
	′H <i>Inspect</i>
onents DWF	Actual
ost Total	Qty Unit Cost Total
otal:	Sub Total:
itai.	
ub To	ub Total:

Page 5 of 6

Measure 8 Smoke/ CO2 Detector Combo					Componen	ts H&S	Inspected			
C	omment									
				Estimated				Actual		
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total	
1	Health and Safety Items	Smoke/CO2 Detector Combo	Each	1						
2	Labor	Labor	Hour	1						
(Other Detail									
				Measur	e Sub Total:] :	Sub Total:		
	Field Notes:									
			Work Or	der Gra	nd Total:		Gran	d Total:		